


AMERICAN & OHIO LOCOMOTIVE CRANE CO. INC.

811 Hopley Avenue P.O. Box 511 Bucyrus, Ohio 44820

800-993-6446 ~ 419-562-6010 ~ Fax: 419-562-2565 ~ www.aolcrane.com

OEM Product Support Bulletin No. 48

DATE:	September 17, 2013	
SUBJECT:	OHIO SWING PINION LUBRICATION UPDATE	
		Kit Part #: 122326
RATING:	DIRECTIVE (Action is required)	☐ ALERT
	☐ INFORMATION	PRODUCT IMPROVEMENT (Enhance Product)
Machine Model (s):	All Ohio DE's	
Serial Numbers:	All Ohio DE's with Lubrication Valve System	
Summary:	This kit replaces the existing Lubrication Valve	
Operational Impact:	 More efficient and positive lubrication System cannot fail due to cold weather or condensation Air is no longer required for lubrication Easy to install and designed for retrofit. Eliminates a Lubrication Valve to failure. Daily lubrication is still required. 	
Warrantv:	n/a	



- Disconnect existing Grease Line and Air Line
- Remove Existing Defective Lubrication Valve
- Install new Kit only connecting the existing Grease Line. Adjust Rubber Lube Hose so it is 1/16" away from the Swing Pinion Gear.
- Shut-off/disconnect air supply Air is no longer required.
- Continue to Grease "Daily" while rotating Upper Machinery Deck 360°. For machines that are equipped with Pile Driver (Hammer), lubrication is only needed for the swing sector you are working within.